

CERRO COPPER PRODUCTS

A Division of The CERRO-MARMON CORPORATION

P. O. Box 681, East St. Louis, Illinois 62202, 618/337-6000

August 13, 1976

153959

Calspan Corporation
4455 Genesee Street
Buffalo, New York 14221

Attention: Mr. J. G. Michalovic

Gentlemen:


Under a separate cover I am sending you the composite water samples you requested. These samples were taken from the inlet and outlet of our Number 6 Scrubber Settling Tank. These samples were taken over a 24-hour period. Samples were collected at 1 P.M. and 8 P.M. on August 12th and 2 A.M. and 7 A.M. on August 13th.

There are three sets of samples, each set has an inlet sample and an outlet sample. The first set represents the raw untreated water. The second set has been acidified with H_2SO_4 to $pH < 2$ and packaged in glass containers. The third set has been acidified with HNO_3 to $pH < 2$.

If we can be of any further assistance, please feel free to contact us.

Very truly yours,

CERRO COPPER PRODUCTS
DIVISION OF CERRO-MARMON CORPORATION


John Schuster
Senior Chemist

J3/lh

bcc: P. Tandler

File

1104